

COMPRESSION TOOL AND DIE INFORMATION FOR COMPRESSION TERMINALS

Die Ref.	BURNDY											KEARNEY						ALCOA										
	Tools, Dies and number of Crimps											Tools, Dies and number of Crimps						Tools, Dies and number of Crimps										
	Y34A		Y35		Y48B		Y486RB		Y60B			WH-1		WH-2		PH-60		12A, 12HA		B		60A		P1,H,H2 H2H				
Index	Dies	Cr.	Dies	Cr.	Dies	Cr.	Dies	Cr.	Dies	Cr.	Die Size	Dies	Cr.	Dies	Cr.	Dies	Cr.	Dies	Cr.	Dies	Cr.	Dies	Cr.	Dies	Cr.			
0.640	243	A243	3	U243	3	C243	2			L243		5/8	18865	7				B73AH	2									
0.840	249	A249	4	U249	4	C249	2			L249			18868	7	36476	7		B74AH	2									
1.000	251	A251	6	U251	6	C251	3	F251		L251			26565	4	36465	4		B75AH	3	75A	2							
1.125	490-547 316	A490 A316	6 6	U490 U316	6 6	C490 C316	3 2	F490 F316	3 2	L490 L316		1 1/8	20636	6	36463	5		B76AH	4									
1.312	327 317-426 300			U327 U317 U34ART	7 7 10	C327 C317 C34AR	3 3 5	F327 F317 F34AR	3 3 5	L327 L317		1 5/16			40424	7							6020AH	2	4420AH	2		
1.500	318-261 608			U261 U608	7 7	C261 C608	3 3	F261 F608	3 3	L261 L608							K6024AH						6024 6024AH	3 3	4424 4424AH	2 2		
1.625	301					C39AR	4	F39AR	4	L724 LJ9ART							K6027AH	2					6026 6027AH	3 3	4426 4427AH	2 2		
1.843	292-578 302 319					C292 C44AR C319	3 4 3	F292 F44AR F319	3 4 3	L292 L44ART L319							K6030AH	2					6028 6030AH	3 3	4428 4430AH 4429	2 2 3		
2.125	422 575					C575	4	F422 F575	4 4	L422 L575							K6034AH	4						6034AH	4	4434AH	4	
2.375	478							F46AR	4								K6030AH	4							6038AH	4	4438AH	4
2.750																								6044AH	4	4444AH	4	
2.937																								6048AH	4	4448AH	4	

2.50 2.592 T&B 212 + AICOA 6040 ATL